

Date: Thursday, 6/22/2006 9:44:14 AM
 User: Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.		Drawing Name	: D3121-043	
Job Number	: 27661		Part Number	: D312113	
Estimate Number	: 10804		Drawing Number	: DISASSEMBLE	
P.O. Number	: N/A		Project Number	: N/A	
This Issue	: 6/22/2006	S.O. No.	: N/A	Drawing Revision	: N/A
Prsht Rev.	: NC		Material	: N/A	
First Issue	: 6/22/2006	Type	: N/A	Due Date	: 6/23/2006
Previous Run	: 00015		Qty:	1	Um: Each
Written By	: SEE ABOVE DATE & USE				
Checked & Approved By	: V L V L C C C C				
Comment	:				

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
		 Comment: SMALL & MEDIUM FAB RESOURCE 1 REMOVE FROM STK 1 X D3121-043 B 244699 DISASSEMBLE BEARING AND BOLTS CONFIRM TO RESTOCK OR SCRAP RESTOCK P/N D3121-13 B/N B 242241 B 24475B <i>RE STOCK SCRAP PN D3121-13 B/N B 244777</i> SB 06/06/22 (1)
2.0	PACKAGING 1	PACKAGING RESOURCE #1
		 Comment: PACKAGING RESOURCE #1 <i>RE STOCK D3121-13 WITH NEW B/N</i> 06-06-20 (1)
3.0	DC	DOCUMENT CONTROL
		 Comment: DOCUMENT CONTROL INSPECT LEVEL 21 D 06/06/22 (1)

Job Completion



U 06-06-22